



MICHAEL R. STYLER Executive Director JOHN R. BAZA
Division Director

# Inspection Report Minerals Regulatory Program Report Date: September 29, 2006

Supervisor Det

Mine Name: Millcreek 1-2-3 Operator Name: Mike Dettamanti

> P.O. Box 291 Kanab, Utah 84741

Inspector(s): Doug Jensen Other Participants: None Mine Status: Inactive Permit number: S/053/051 Date: September 14, 2006 Time: 11:30 AM

Weather: Cool, light rain

**Elements of Inspection** Evaluated Comment Enforcement 1. Permits, Revisions, Transfer, Bonds 2. Public Safety (shafts, adits, trash, signs, highwalls) 3. Protection of Drainages / Erosion Control 4. Deleterious Material 5. Roads (maintenance, surfacing, dust control, safety) 6. Concurrent Reclamation 7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes) 8. Water Impoundments 9. Soils 10. Revegetation 11. Air Quality 12. Other

### **Purpose of Inspection:**

Inspected the site while I was in the area.

#### **Directions to Site:**

See previous inspection report.

## **Inspection Summary:**

The site remains unchanged since my last visit on February 27, 2006.

## Conclusions and Recommendations:

I will continue to monitor the site when I am in the area.

Inspector's Signature Long Jensen Date: 9/29/06

dj:pb

cc:

Mike Dettamanti

Steve Winslow, USFS, Beaver Ranger District

 $O: \label{lem:constraint} O: \label{lem:constraint} O: \label{lem:constraint} Wo 53-Washington \label{lem:constraint} S0 53 00 51-Millcreek 123 \label{lem:constraint} Inspections \label{lem:constraint} O: \label{lem:constraint} Wo 53-Washington \label{lem:constraint} S0 53 00 51-Millcreek \label{lem:constraint} Inspections \label{lem:constraint} S0 53 00 51-Millcreek \label{lem:constraint} O: \label{lem:constraint} Wo 53-Washington \label{lem:constraint} S0 53 00 51-Millcreek \label{lem:constraint} S0 53 00 5$